

## **Design Notes**

## **Mince Pie Stand**

Difficulty Rating:		
Easy	YES	
Straight forward		
More complex		


## Please note:

These Design Notes are for our regular metalcrafters who are familiar with our more comprehensive Design Pack instruction sheets and who are ready to progress on to new projects where briefer outline instructions are sufficient. The dimensions in the diagram(s) shown overleaf are approximate and for guidance only. Where bend angles, rolling radii or other information are not specified it is assumed that the reader is experienced enough with Metalcraft tools to be able to work these out for themselves from the drawings provided.

Tools required to make this design		
Punching	Practical Punch/Shear Tool (PPS) <b>or</b> Master Punch/Shear <b>or</b> XL5+ Power Bender fitted with 3mm Punch Block & Pins.	YES
Cutting	Practical Punch/Shear Tool (PPS) or Master Punch/Shear Tool or XL+ Power Bender Tool	YES
Riveting	Practical Riveting Bending and Rolling Tool (PRBR)	YES
Bending	Practical Riveting Bending and Rolling Tool (PRBR)	YES
Rolling	Practical Riveting Bending and Rolling Tool (PRBR)	YES
Scrolling	Mk 1/2 Scroll Former	YES

We recommend that before starting you wipe all steel bars down so that they are free of grease, scale or dirt. After cutting any component, we also recommend that you trim the corners for a neater finish, if preferred, unless these instructions tell you otherwise. Use a fine tip marker pen, pencil or scribe for marking hole, bend, scroll, roll points on the bars.





## INSTRUCTIONS: MINCE PIE STAND

